


A-3 Assembly Diagram



Contents

Chapter 1 Control system, transmission mechanism on Z-axis

1. Overview of components.....4
2. Installation of mainboard and LCD display.....5
3. Installation of limit switch and motor base on Z-axis...6
4. Installation of power supply on Z-axis.....7
5. Installation of T-shaped nuts.....8

Chapter 2 Transmission mechanism on Y-axis

1. Overview of components10
2. Installation of electric motor and back supporting-block on Y-axis.....11
3. Installation of 688 lip type bearing and front supporting-block.....12
4. Installation of box type bearings13
5. Installation of belt clips on Y-axis Y.....14
6. Installation of screws.....15
7. Installation of aluminum sheets.....16-18
8. Installation of synchronous belt.....19
9. Installation of limit switch on Y-axis.....20
10. Installation of hot bed aluminum substrate.....21
11. Whole Y-axis installed to the main sight board.....22-23

Chapter 3 Transmission mechanism on X-axis

1. Overview of components.....	25
2. Installation of electric motor on X-axis.....	26
3. Installation of 693 bearings with edge.....	27
4. Installation of polished rod and linear bearings.....	28
5.X-axis installed to the lead screw of Z-axis.....	29
6. Installation of fixed block.....	30
7. Installation of synchronous belt on X-axis.....	31-32
8.Installation of cover plate.....	33

Chapter 4 Extrusion mechanism

1. Overview of components.....	35
2. Installation of sprayer suites.....	36
3. Installation of turbofan and guide tuyere	37
4. Installation of limit switch on X-axis.....	38

Chapter 5 Control circuit and frame installation

1. Overview of components.....	40
2. Installation of electric circuits.....	41-49
3. Installation of winding pipes.....	50-52
4. Installation of left and right cover plates.....	52-54


3D 打印机
Printer

Chapter 1 Control system and transmission mechanism on Z-axis

3D 打印机
Printer



Installation of Mainboard



Get the mainboard and main body ready



Align the holes



Screw the mainboard with the plastic screws by allen wrench(4* M3*10 screw)



Complete

Installation of LCD Display



Get the lcd display ready



Align the holes and rubber mat



Screw the lcd display with the plastic screws by allen wrench(4* M3*10 screw)



Complete

Installation of Z-axis limit switch



Get the limit switch ready



Put the cord through the main body



Put the screw M2*16-2pcs through the limit switch and sheathe the 5mm shoot-through column



Use a socket head wrench to tighten the screws




Complete

Installation of Z-axis electric motor



Get the Z-axis lead screw motor and motor fixing seat ready



Use a socket head wrench to tighten the screws: M3*12-8 pcs

The threaded hole of M6 should align with the wiring duct of the lead screw motor




Complete


Z-axis Installation



Get two lead screw motors ready



Align the hole site
(same handling for
left side)



Use a socket head wrench to
tighten the screws: M6*10-4
pcs(same handling for left
side)




Complete

Power Supply Installation



Get the power
supply ready



Align the
hole site



Use a socket head
wrench to tighten
the screws: M3*8-
2pcs



Complete


Installation of T-shaped Nuts to the X-axis motor fixing base



Get the T-shaped nuts and X-axis motor fixing seat ready



Align the holes



Use a socket head wrench to tighten the screws 3*M3*16 and 1*M3*10 screw



Complete

Installation of T-shaped nuts to X-axis motor passive base



Get the T-shaped nuts and X-axis motor driven seat ready



Align the hole



Use a socket head wrench to tighten the screws 3*M3*16 and 1* M3*10.




Complete

3D 打印机
Printer

Chapter 2 Transmission Mechanism on Y-axis


3D 打印机
Printer



Installation of Y-axis motor and back supporting block



Get the Y-axis motor, motor seat and supporting block




Align the hole



Use a socket head wrench to tighten the screws M3*12-3 pcs




Complete



Align the Y-axis motor with the hole of the supporting block



Use a socket head wrench to tighten the screws: M6*10-2pcs




Complete

Installation of 688 bearings with edge and front supporting block



Get the Y-axis supporting block, bearing fixing seat and 688 lip type bearings ready



Align the hole



Use a socket head wrench to tighten the screws M6*10-2 pcs



Put the screw M8 through the bearing fixing seat




Put the 688 lip type bearing into the U-shaped slot (The lip side should be next to the side of the bearing fixing base.)





Tighten the cap, then complete .


Installation of box-type bearings




Get ready 3 box-type bearings
and 1 piece of aluminum sheet



Align the front
and back holes



The other two are the same. Use a socket head wrench to tighten the
screws M4*8-12pcs(not too tight)




Complete

Installation of Y-axis Belt Clip




Y-axis belt clip, install the aluminum sheet of the box-type bearing well

First put 2pcs of screws M3*10 through the aluminum sheet and put on the caps (don not tighten)



Put the U-shaped slot on one end of the Y-axis belt clip through the downside of the screw hole. The other side is the same.




Use the tools to clamp the screw cap and tighten it.



Complete

Installation of M8 Screw Rod



Get ready 2 screws of M8*410 and 16 screw caps of M8 (Only use 12 caps, the rest 4 will be tightened on the screw rod
Spacer: M8-12 pieces



Install following the order: screw cap--spacer*2pcs—screw cap—screw cap--spacer*1pc; Reverse the screw rod, screw cap--spacer*1pc



The other one screw rod is the same, These screw caps cannot be tightened.
Complete



Installation of aluminum sheets




Get ready 2 slick rods $\varnothing 8 \times 380$ -
2pcs and the modules on pages
7, 8 10 and 11.



3D 打印机
Printer



Install the slick rod into the Y-axis motor supporting block and the protruded part should align with the Y-axis motor supporting block.



Install the screw rod from the downside of the
slick rod and put the box-type bearings on the
aluminum sheet through the slick rod.




Install one end of the slick rod into the supporting block of the 688 lip
type bearings and the slick rod should align with the surface of the
supporting block.


3D 打印机
Printer



Screw the cap outside to the supporting block. The other one is the same.



The protruded two ends should be equal in length. The other one is the same.



Fill up the cap on the protruded screw.



Use a solid wrench to tighten




After tightening the screw rod, screw
one cap.



Use a solid
wrench to
tighten.



Slide the aluminum sheet
with hand to see whether it
moves smoothly.



Adjust the upper screws according
to the tightness, but not too tight.



Complete

Installation of synchronous belt



Get ready the synchronous belt




Turn over the aluminum sheet



Imbed the synchronous belt into the belt clip and turn back the synchronous belt and tighten it with a ribbon.



The side with synchronous teeth round passing the bearing and synchronous wheel




Imbed the other end into the belt clip and turn it back. Use the ribbon to tighten and tools to cut the redundant ribbon head. Complete

Installation of Y-axis limit switch




Get ready the Y-axis limit switch



Install the switch on the supporting block with two box-type bearings and next to the Y-axis motor




The shrapnel of the limit switch is toward the box-type bearings. Use the socket head wrench to tighten the screws M2*10-2pcs




Box-type bearings should thoroughly bear the shrapnel of the lower limit switch. Complete




Installation of hot bed




Get ready the aluminum substrate (Do not tear the blue-colored paper off.)




Put the aluminum substrate on the aluminum sheet and the wiring duct should be toward the Y-axis motor



Tighten the 4 screws M3*25 and 4 springs and 4 butterfly caps



Install the spring between the aluminum substrate and aluminum sheet, and install the screw M3 through the aluminum substrate and sheet. Then tighten the butterfly cap.



Complete


Whole Y-axis installed to main body




Put the components of Y-axis next to the cap of the motor (a bit loose)



The Y-axis module screw cap after the alignment with the U-shaped slot fixed with the back end of the batter board




The Y-axis module screw cap after the alignment with the U-shaped slot fixed with the middle end of the batter board



After aligning the hole, check the tightness of the synchronous belt.



If it is a bit loose, then screw outside the left cap to a certain distance; if it is a bit tightened, then screw inside the left cap to a certain distance (The supporting block also moves inside or outside). Until the synchronous belt is properly tight, then tighten the screw cap.



The back screw cap should be tight to the surface. Then tighten it.



Use hands to test whether the platform moves smoothly.
Complete

3D 打印机
Printer

Chapter 3 Transmission mechanism on X-axis

3D 打印机
Printer




Installation of X-axis motor




Get ready the X-axis motor and motor seat



Align the hole site



Install 4 screws M3*20-4 pcs



Use the socket head wrench to tighten



The wiring duct of the motor should be downward. complete.


Installation of 693 bearings with edge



Get ready the X-axis driven seat and two 693 lip type bearings




Put the screw M3*16 through one side of the X-axis driven seat.




Install the 693 lip type bearings and its side should align with the side for the X-axis driven seat.



Similarly, install another lip type bearing and the screw cap.



Use the socket head wrench to tighten the screws.



Complete


Installation of polished rod and linear bearings



3D 打印机
Printer

Get ready two slick rods of $\phi 8 \times 380$, one long and short linear bearing each, and assembled modules.

Insert the slick rod to the mounting hole.



3D 打印机
Printer


Install the linear bearing and X-axis driven seat.
The slick rod should be flat and smooth.

Install one short and long moving bearings
and insert them into the mounting holes.
Complete

Whole X-axis installed to Z axis lead screw




Get ready the X-axis and batter board



While installing, avoid the knob of the display screen and align the whole of the T-shaped nut.



Screw the slick rod with both hands to see whether it moves smoothly. If it doesn't move smoothly, it is required to move the X-axis motor seat or driven seat inwardly a certain distance until the slick rod can be smoothly screwed. Then install the $\phi 8 \times 321-2$ to the Z-axis motor mounting holes.




Revolve the slick rod to see whether it will be stuck or not.
Complete


Installation of fixing base



Get ready the fixing seat, and install the screws M3*5-2pcs



Align the screws hole to the light but do not tighten them.






Align the two holes and tighten the screws M6*10-2pcs. The other side is the same. And use the socket head wrench to tighten them.




Finally tighten the screw and Complete.

Installation of X-axis synchronous belt





Check the hole .


Get ready the sprayer mounting seat, cover plate, synchronous belt, ribbon and countersunk head screws M3*10 and 8 self tapping screw caps.




Align the hole site.




Take one synchronous belt and align one end of teeth and round it back.




Bind it up with the ribbon.




The other end of the belt rounds through the lip type bearing in the driven seat.




Continue to round it through the synchronous teeth in the X-axis motor seat. The rounding order will vary with the installation order.



Align the teeth.




Fasten with the ribbon.




Complete

Installation of the cover plate




Put the side with the countersink outward, and align the hole site.




Install one countersink self tapping cross screw M3*10



Tighten it with a cross screwdriver




Install the other end symmetrically




Install the rest 6 screws,
Complete


3D 打印机
Printer

Note: after installation, use hands to move backward and forward to feel the tightness of the synchronous belt. If it is hard to move, it is required to loosen the belt a bit; if it moves unevenly, it should be bit tightened.




Chapter 4 Extrusion Mechanism







Installation of MK8 Extruder




Get ready the
sprayer suites



Align the hole site



Fix with one cross self tapping
screw M3*10




Use a cross screwdriver to tighten and install another
two by turn. Complete


Installation of turbofan and tuyere




Get ready the turbofan and tuyere.




The side with the nameplate of turbofan faces inside and aligns the hole.




Install 2pcs of screws.



Use the socket head wrench to tighten.




Align the tuyere with the air outlet of the turbofan and install.




Complete


Installation of X-axis limit switch




Get ready the X-axis limit switch and two self tapping screws M2*10.




Align the hole of the limit switch with the hole of the sprayer seat.



Install the self tapping screw M2*10.



Use the small cross screwdriver to tighten the screws.



Complete




Move the whole sprayer limit switch to see whether it can touch the X-axis motor seat.

3D 打印机
Printer

Chapter 5 Installation of Control Circuit and Frame

3D 打印机
Printer



Installation of power switch line

Note: In order to let the customers more directly understand the structure of the equipment, here several pictures are specially explained as follows.





Connect the AC socket line to the AC switch.



Connect the AC switch line to the power supply.



Connect the 12V power supply to the mainboard.



Put the red and black lines of the square fan through the hole of the batter board, and connect them to the terminal together with the 12V power supply line. Complete


Installation of LD display line



Connect the sockets to the display screen.




Connect another socket.




Connect the other end to the control hole of the mainboard.


Installation of extrusion motor line



Connect the extrusion motor line to the motor.




The other end puts through the hole of the batter board.



Then other end is connected to the control hole of the mainboard.


Installation of Z-axis motor



Connect the Z-axis motor line to the control hole of the mainboard.



The end with shorter lien is connected to the left motor.




The end with longer line is connected to the right motor.

Installation of Y-axis motor



Connect the Y-axis motor line to the control hole of the mainboard.




The other end is connected to the Y-axis motor.


Installation of X-axis motor



First put one end of the X-axis motor line through the downside hole of the batter board.




And connect it to the control hole of the mainboard.




The other end is connected to the X-axis motor.

Installation of Z-axis limit switch line




One line of the Z-axis limit switch




It is connected to the jack of the mainboard.

Installation of Y-axis limit switch line




One line of the Y-axis limit switch



It is connected to the jack of the mainboard.

Installation of X-axis limit switch line



One line of the X-axis limit switch




It is connected to the hole of the mainboard.

Installation of hot bed line and temperature sensor line




Connect the hot bed line.




Strip off the red and black wire head of the other end to show the wire cores.



Press tightly on the mainboard terminal.




One line of the temperature detection line




It is connected to the A14 pin of the mainboard.


Installation of sprayer temperature sensor line



Unfasten the sprayer temperature detection line




Put it through the hole of the batter board.




It is connected to the A13 pin of the mainboard.


Installation of turbofan line



Unfasten the turbofan line



Put it through the hole of the batter board.




Press it tightly on the mainbaord terminal.

Installation of extruder heating cable




Unfasten the sprayer heating lines.



Put the line through the hole of the batter board.




Use the tool to strip off the cord.



Press it tightly on the terminal.

Cable diagram of the mainboard


Note: After finished the cables connection, please check according to the diagram again.



Installation of Y-axis winding tube




Align one end of the winding tube with one end of the hot bed line.



The winding tube is wound up the hot bed line.




The winding tube after winding



The whole Y-axis winding tubes after winding

Installation of the extrusion winding tubes




Align one end of the winding tube with all the lines on the sprayer (and leave certain margin; do not pull too tight.)



When the winding tube wraps the hole of the batter board, it is required to cut a certain length.




Put the shortened winding tube through the hole of the batter board.




There should be a certain length when passing through the hole.


Installation of the X-axis winding tubes



Align one end of the winding tube to the X-axis motor line




Wrap the winding tube.




Complete

Installation of the right cover



Get ready the right plate.



Align the back side hole site.




Install the screws M3*6-4pcs.



Align the front side hole.




Install the three screws M3*6.



Use the socket head wrench to tighten all the screws ,complete

Installation of the left cover



Get ready the left cover plate.




Align the back side hole.



Install the four screws M3*6.



Align the front side hole.



Install the three
screws M3*6.



Use the socket head wrench to
tighten all the screws ,complete.

Pls assembly the printer follow this above assembly
diagrams and printing videos together.

3D 打印机
Printer